



Customer Name
Address
Email
Year
Appointment #

Cody Johnson
1012 N. Santa Fe Avenue, Princeville, IL 61559
cjohnson@greenfield-contractors.com
2025
999999-9

Preventative Maintenance Inspection Sheet

N/A	Repaired
	Acceptable
	Recommend Replacement
	Needs Replacement

1	Cover Rubbing Foundation		X		
2	Landscape interference		X		
3	Eaves		X		
4	Batton Stripping		X		
5	Main Cover Condition		X		
6	Existing Patches		X		
7	Interior Stand Off Pipe		X		
8	Back End Wall Cover		X		
9	Back Vents on End Wall		X		
10	Back Ground Flap In End Wall		X		
11	Back Conestoga Fabric / Winch		X		
12	Back Fabric Door on End Wall	X			
13	Back Walk Doors on End Wall	X			
14	Foundation		X		
15	Pull Pipe Exterior		X		
16	Framed Openings (Conveyors)		X		
17	Front End Wall Cover		X		
18	Front Vent on End Wall		X		
19	Front Ground Flap on End Wall		X		
20	Front Conestoga Fabric / Winch		X		
21	Front Fabric Door on End Wall		X		
22	Front Walk Doors on End Wall		X		
23	Exterior 2" Winches				X
24	Exterior 2" Straps				X
25	Cover Rubbing on Steel Side #1		X		
26	Cover Rubbing on Steel Side #2		X		
27	1" Ratchets		X		
28	Interior 2" Winches			X	
29	Interior 2" Straps			X	
30	Pull Pipe Interior		X		
31	Truss Leg Integrity		X		
32	Truss Leg Anchor Bolts		X		
33	Structural Cables		X		
34	Purlins / Braces		X		
35	Truss Integrity		X		

Prev. Maint. Sticker Yes

Main Cover Type

End Wall Type

Recommendations:

We recommend replacing the exterior winches and straps.

Notes

