

1012 N Santa Fe Ave  
Princeville Il, 61559  
United States

**Customer:**

Richard Frail  
✉ rfrail@greenfield-contractors.com

## Good

<u>Service Check</u>	<u>Status</u>
Back Vents on endwall	Good
Foundation	Good
Front Vents on endwall	Good
Cover rubbing on Steel Side #1	Good
Cover rubbing on Steel Side #2	Good
Truss Leg Integrity	Good
Truss Anchor Bolts	Good
Purlins/Braces (get picture for type)	Good
Truss Integrity (state location of damage)	Good

## Serviced

<u>Service Check</u>	<u>Status</u>	<u>Repairs</u>
Cover Rubbing on Foundation	Serviced	Rubbing: Add rub rails, Rubbing: Repair cover
the cover was rubbing going down the concrete blocks i added rubrail and fixed the holes in the cover		
Outside Landscaping	Serviced	Branches to cut

1012 N Santa Fe Ave  
 Princeville Il, 61559  
 United States

a few branches were getting close to the foundation so i trimmed them up so that they dont get into the cover

<b>Greenfield Sticker</b>	Serviced	Add Sticker
<b>Front Conestoga over endwall</b>	Serviced	Tension: Retension 2" winches
<b>Main Cover Condition</b>	Serviced	Retension Entire Cover
<b>Back End Wall Cover</b>	Serviced	Tension: Retension Entire Cover
<b>Back Conestoga over endwall</b>	Serviced	Tension: Retension Entire Cover
<b>Back Fabric Door on endwall (operate 2 cycles)</b>	Serviced	Pully tested and greased.
<b>Back Walkdoors on endwall (Open/Close)</b>	Serviced	Lubed hinges
<b>Front End Wall cover</b>	Serviced	Tension: Tighten
<b>Exterior 2" Winches (Test 4-6)</b>	Serviced	Tension: loosen, tighten bolt, retighten all
<b>Exterior 2" Straps (Test 4-6)</b>	Serviced	Tension: Tighten
<b>1" Ratchets (Test 4-6)</b>	Serviced	Tension: Tighten
<b>Structural Cables</b>	Serviced	Nuts against turnbuckle: Tighten

## Quote Needed

<u>Service Check</u>	<u>Status</u>	<u>Repairs</u>
Pull Pipe Exterior	N/A	Bent: ADD WINCHES, Add Fender Washers

N/A

<u>Service Check</u>	<u>Status</u>
----------------------	---------------

---

**Greenfield Contractors LLC**

1012 N Santa Fe Ave  
Princeville Il, 61559  
United States

<b>Front Ground Flap in endwall</b>	N/A
<b>Existing Patches:</b>	N/A
<b>Back Ground Flap in endwall</b>	N/A
<b>Pull Pipe Exterior</b>	N/A
<b>Front Fabric Door on endwall (operate 2N/A cycles)</b>	N/A
<b>Front Walkdoors on endwall (Open/Close)</b>	N/A
<b>Interior 2" Winches (Test 4-6)</b>	N/A
<b>Interior 2" Straps (Test 4-6)</b>	N/A
<b>Pull Pipe Interior</b>	N/A

**Comments/Notes:**

Greenfield Contractors assumes no liability for building warranty.

The above items listed for Needs Repair may affect warranty if not serviced promptly.

PM Richard Frail and Phone # (309) 385-1859

Repair Quote to follow for item that Need Repair.

A Full Structural analysis of Trusses and Foundation was not completed, if desired, seek 3rd party assessment.